



X2C/ X2C LT FOLDING LINES






2/3











Put the orange LCL line (pic.1) through the loop on the profile and pull it tight. Repeat this step up to Rib 30 (line al2).

Put the yellow LCL line (pic.2) through the A loop on Rib 33 (line al3).

Connect the toplines from ala to al3 with a larks head knot to the LCL lines.

Connect all lines like on the lineplan

XI Crossline top side is connected with ala and a2a line (pic.5).



The X1 crossline bottom side is connected with the riser on the opposite side!

Push the folding riser through the upper pulley connection webbing (pic.6).

Connect the main lines with the folding riser.

Close the maillons with a tool and mount the inserts.

Before flight you have to check that the folding lines are loose and not under tension!



Check that there is no twist in the lines!



The maillons should be closed with a tool and the insert should be mounted!

V1_2024